

# SKF4153- PLANT DESIGN


## HEAT INTEGRATION

Prof. Dr. Zainuddin Abdul Manan


Ir. Dr. Sharifah Rafidah Wan Alwi



Process  
B-4  
integration




T- $\Delta H$  Plot




## Heat Recovery Problem

Stream that needs heating -  
A “*cold*” stream (heat sink)



***Steam is used for heating***

Stream that needs cooling -  
A “*hot*” stream (heat source)




***Cooling water is used for cooling***

Consider heat exchange between the process streams to save hot utility (steam) and cold utility (cooling water).

## How Much Heating Is Needed?

A Cold Stream (that needs heating)




Heat Capacity Flowrate $FC_p$ (MW/K)	Enthalpy Change $\Delta H$ (MW)
2.0	?

$$\begin{aligned}
 \Delta H &= FC_p \Delta T \\
 &= FC_p (T_{\text{target}} - T_{\text{supply}}) \\
 &= 2.0 (130^{\circ}\text{C} - 40^{\circ}\text{C}) \\
 &= 180 \text{ MW}
 \end{aligned}$$

## How Much Cooling Is Needed?

A Hot Stream (that needs cooling)




Heat Capacity Flowrate $FC_p$ (MW/K)	Enthalpy Change $\Delta H$ (MW)
1.0	?

$$\begin{aligned}
 \Delta H &= FC_p \Delta T \\
 &= FC_p (T_{\text{target}} - T_{\text{supply}}) \\
 &= 1.0 (50^{\circ}\text{C} - 200^{\circ}\text{C}) \\
 &= -150 \text{ MW}
 \end{aligned}$$


## Heat Exchange Between Process Streams

Stream Number	Stream Type	$T_{\text{supply}}$ ( $^{\circ}\text{C}$ )	$T_{\text{target}}$ ( $^{\circ}\text{C}$ )	$FC_P$ (MW/K)	$\Delta H$ (MW)
1	Cold	40	130	2.0	180
2	Hot	200	50	1.0	150

*Before Integration*



*After Integration*



A process to process heat exchanger

**83% Saving On heating**  
**100% Saving On cooling**

## Pinch Design Targets

A systematic tool to design heat recovery networks for maximum energy recovery

Targets set ahead of design.....

(Use 1st Law of Thermodynamics)

What are the:

- Minimum heating requirement (Usually Steam Rate)
- Minimum cooling requirement (Usually CW Rate)
- Minimum number of units

## Process Energy Targets

Process *energy targets* (steam and cooling water requirements) can be obtained from,

### ☆ *Composite Curves*

- cumulative process heat availability (surplus)
- cumulative process heat requirement (deficit)

### 🕒 *Problem Table* Algorithm

- process heat surpluses and deficits within some specified temperature intervals




# Composite Curve

## Temperature - Enthalpy Diagram

Given the stream Information :

Stream Number	Stream Type	$T_{\text{supply}}$ ( $^{\circ}\text{C}$ )	$T_{\text{target}}$ ( $^{\circ}\text{C}$ )	$FC_p$ (MW/K)	$\Delta H$ (MW)
1	Cold	40	130	2.0	180





☒  $\Delta H$  is a relative quantity. Thus, the  $\Delta T$ - $\Delta H$  curves can be shifted horizontally

☒  $1/FC_p$  is the slope of the  $\Delta T$ - $\Delta H$  curve


## The Approach

Stream Number	Stream Type	$T_{\text{supply}}$ ( $^{\circ}\text{C}$ )	$T_{\text{target}}$ ( $^{\circ}\text{C}$ )	$FC_P$ (MW/K)	$\Delta H$ (MW)
1	Hot	400	120	1.0	-280
2	Hot	340	120	2.0	-440
3	Cold	160	400	1.5	360
4	Cold	100	250	1.3	195





# The "Pinch"

Hot and cold composites on the same  $\Delta T$ - $\Delta H$  diagram




## Hot and cold composites on the same $\Delta T$ - $\Delta H$ diagram







## Effect of $\Delta T_{\min}$



Process  
with integration

\* $\Delta T_{\min}$  =  
the smallest  
approach  
temperature ( $\Delta T$ )  
for heat exchange



## Significance of The "Pinch"

- The two composites can be moved horizontally to approach one another but is limited by a minimum approach temperature,  $\Delta T_{\min}$
- There should be no heat transfer across the pinch.
  - ❖ Do not heat below the pinch (no external heating)
  - ❖ Do not cool above the pinch (external cooling)
  - ❖ Do not transfer heat across the pinch
- Any external cooling above the pinch, or heating below the pinch will result in cross pinch heat transfer, thereby increasing the external heating requirement



## Exercise

Stream data

$$\Delta T_{\min} = 10^{\circ}\text{C}$$

Stream	Type	T supply ( $^{\circ}\text{C}$ )	T target ( $^{\circ}\text{C}$ )	$\text{FC}_P$ (MW/K)
C1	Cold	20	135	2
C2	Cold	80	140	4
H1	Hot	170	60	3
H2	Hot	150	30	1.5

Verify that  $Q_{\text{H,min}} = 20\text{MW}$ ;  $Q_{\text{C,min}} = 60\text{MW}$

# Problem Table Algorithm


## Global Temperature Interval

Actual Temperatures

	$T_S$	$T_T$
C1	60°	160°
C2	116°	260°
H1	160°	93°
H <sub>2</sub>	249°	138°

Shifted Temperatures

	$T_S$	$T_T$
C1	65°	165°
C2	121°	265°
H1	155°	88°
H2	244°	133°




-----	Actual
—————	Shifted

Hot:  $-\Delta T_{\min}/2$   
 Cold:  $+\Delta T_{\min}/2$


## Remove Duplicates, and Set Up Global Temperature Intervals

Stream	$\frac{T_S}{T_T}$	Remove Duplicates (if any)	Set up Intervals
C1	<u>25</u> →	25	---- 165 ----
	140 →	140	---- 145 ----
C2	<u>85</u> →	85	---- 140 ----
	145 →	145	---- 85 ----
H1	<u>165</u> →	165	---- 55 ----
	55 →	55	---- 25 ----
H2	<u>145</u> →	duplicate	
	25 →	duplicate	

## Problem Table with Global $T_{int}$



# Heat Cascade



## Problem Table - Procedure Summary

- Get shifted  $T_S$ ,  $T_T$  and  $T_{int}$
- Do interval heat balances - get int. heat surpluses and deficits
- Cascade from higher to lower  $T_s$
- Cascade for positive heat flows between intervals
- Add the largest negative heat flow
- Find  $T_{Pinch}$ ,  $Q_{Hmin}$  and  $Q_{Cmin}$

## Results Summary

- ✉ Minimum Process Heating Requirement from Hot Utility (e.g. steam) = 127.68 MW
- ✉ Minimum Process Cooling Requirement from Cold Utility (e.g. cooling water) = 250.14 MW
- ✉ Pinch (Interval) Temperature = 244 °C
- ✉ For  $\Delta T_{\min} = 10^{\circ}\text{C}$
- ✉ Hot Stream Pinch Temperature = 249°C
- ✉ Cold Stream Pinch Temperature = 239°C

## Give yourself a TRY

Stream No.	Stream type	Supply Temperature, $T_S$ ( $^{\circ}\text{C}$ )	Target Temperature, $T_T$ ( $^{\circ}\text{C}$ )	Heat capacity flow rate, $FC_p$ ( $\text{kW}/^{\circ}\text{C}$ )
1	Hot	120	86	10.99
2	Hot	260	160	6.04
3	Hot	83.3	70	13.13
4	Hot	160	50	6.56
5	Cold	50	97	11.83
6	Cold	104	124	14.89
7	Cold	86	230	5.69



## References

- J.M. Douglas, Conceptual Design of Chemical Processes, McGraw Hill, 1998.
- L.T. Biegler, I.E. Grossman, A.W. Westerberg, Systematic Methods of Chemical Process Design, Prentice Hall, 1997.
- Monograph, Process Design and Synthesis, Universiti Teknologi Malaysia, 2006/07
- R. Smith, Chemical Process Design, McGraw Hill, 1995.
- W.D. Seider, J.D. Seider, D.R. Lewin, Product and Process Design Principles: Synthesis, Analysis and Evaluation, John Wiley and Sons, Inc., 2010.